I hereby certify that this correspondence is being deposited with the United States Postal Service as First Class Mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria VA 22313-1450. On Name Date IN THE UNITED STATES PATENT AND TRADEMARK OFFICE Atty Docket: 10003851-03-US 7,307,413 December 11, 2007 McKim, Jr. DEVICE USING A DETECTION CIRCUIT TO DETERMINE WHETHER AN OUTPUT CURRENT THEREOF IS SOURCE-INDUCED OR LOAD-INDUCED, AND METHOD REQUEST FOR ISSUANCE OF **CERTIFICATE OF CORRECTION** Attn: Certificate of Correction Branch Commissioner for Patents Alexandria VA 22313-1450 Agilent Technologies, Inc., assignee of the entire interest in the above-identified patent, respectfully requests that a Certificate of Correction be issued in accordance with 37 C.F.R. 1.322 Enclosed herewith is a completed copy of Form PTO/SB/44 describing the various errors involved in the above-identified patent.

1. The errors are a result of USPTO mistake. NO FEE is required.

Patent No.:

Inventor(s):

THEREFOR

P.O. Box 1450

and/or 1.323.

Sir:

Issued:

Title:

2. The errors are a result of Applicant's mistake. \$100 Fee required.

3. The errors are a result of both USPTO and Applicant's mistakes. \$100 Fee required.

If boxes 2 or 3 above are checked, please charge the \$100.00 fee as set forth in 1.20(a), for Applicant's errors (37 C.F.R. 1.323), to our Deposit Account 50-1078. A duplicate copy of this letter is enclosed.

Issuance of a Certificate of Correction to correct these errors, which occurred in good faith is therefore respectfully requested. We shall appreciate your returning to us an executed copy of this Certificate of Correction for attachment to our Letters Patent.

Respectfully submitted,

By: /James C. Pintner/

James C. Pintner Reg. No. 33,272

AGILENT TECHNOLOGIES, INC. Legal Department, DL 429 Intellectual Property Administration P.O. Box 7599 Loveland, Colorado 80537-0599 Phone No. (970)679-3238 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

	Page <u>1</u> of <u>1</u>	
PATENT NO. 7,307,413		
APPLICATION NO.: 10/826,263		
SSUE DATE : December 11, 2007		
INVENTOR(S) : McKim, Jr.	·	
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:		
In column 24, line 19, in Claim 14, delete "ioop" and insert loop, therefor.		
	ļ	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.